JSM2/JSK2/JSC3/JSC4 Series

Applications

This product can be used with devices and equipment requiring the following of functions.

When multipoint positioning is required (transfer/positioning)

The equipment can be accurately stopped at several required positions.

2 When position locking is required

The brakes can be applied and held instantly when the air source or power is turned OFF (during power failure or accident), preventing equipment damage and securing safety. 3 When emergency stop is required

The cylinder can be immediately stopped with electric signals, etc., when a worker enters a hazardous area.

LCM

LCR LCG

LCW I CX

STM STG

STS/ST

STR2

UCA2

ULK* JSK/M2

JSG

JSC3/JSC

USSD **UFCD**

USC

LMB I MI **HCM**

НСА LBC

CAC4

UCAC2

CAC-N

UCAC-N RCS2 RCC2

PCC

SHC MCP

GLC MFC BBS RRC

GRC RV3 NHS HRL

LN Hand

Chuk

MecHnd/Chu

ShkAbs

Ending

FJ

FΚ SpdConti


UB JSB3

Workpiece lock

When locking the workpiece to the jig or mounting base, etc., it can be locked even if there is no pneumatic source or power. The workpiece can be transferred while locked to the jig.


Applications

Linear multipoint welding When welding steel plates, etc., linearly at several points, this cylinder can be used to move and position the slide table or welding gun. Welding gun




4 Movement to conveyor Move products to the conveyor one at a time. Move products to the conveyor one at a time Product î Air cylinder Conveyor

2 Position locking If there is a load in the vertical direction and the load could fall under its own weight when the pressure source is cut off, the brakes will be applied to prevent falling. Air cylinder




5 When several cylinders with different strokes are required

> When different-sized products are in motion on a conveyor, etc., in many cases the stroke length for the cylinders set there must also be changed. Using the brake cylinder, a cylinder compatible with different strokes is created electrically.



Workpiece lock When locking the workpiece to the jig, etc., if the brake cylinder is used, it will be locked even when the pneumatic source or power is OFF. Workpiece



6 Hopper open/close

> In the case where a hopper must be closed at a specific weight in powder manufacturing, accurate measurement is obtained by stopping the hopper, measuring it accurately and then completely closing it.

